

**DATE: 02/22/2021**

**INVESTIGATOR: Neal Heil**

**WEATHER: Partly cloudy, WNW wind 5-10 mph, 34 degrees F**

**STOP 1 – HIGHWAY 66 WEST of  
ASHLAND GUN CLUB**

Water/liquid present. No unusual odors noted.



**STOP 2 – North of the Intersection of  
COUNTY ROADS 6 & F**




Fresh snowfall and ice observed upstream from culvert. No flow observed entering culvert. No flow observed leaving downstream opening of culvert.



**STOP 3 – Road 7/Highway 66**

Sandbags rearranged since my previous visit and blue nylon rope leading into entrance to culvert. Brownish liquid observed in hole chopped into ice prior to my visit. Called Brad Pracheil to advise liquid presumed to be spilled material present at this location.



<p><b><u>STOP 4 – County Road 8, North of Road H</u></b></p> <p>Brownish-colored ice present below fresh layer of snow; same as previous visit.</p>	
<p><b><u>STOP 5 – UN-L Eastern Extension – North of County Roads 9 &amp; J</u></b></p> <p>Liquid observed upstream of road. Downstream snow-covered. Generator present, but not running. Hoses present, but not connected to anything.</p>	
<p><b><u>STOP 6 – ALTEN LLC FACILITY DIGESTERS</u></b></p> <p>Truck with “Bucklin” on door and three workers present at south digester. Using gasoline-powered pump to pump from digester piping vault to lagoon immediately east of south digester. Lagoon contains liquid within 5-10 feet of top of berm. I was told no flow out of south digester. North digester as before (no observed leaks). Several workers using hose emitting steam to melt large ice structure on south side of north digester.</p>	

**ADDITIONAL INFORMATION / COMMENTS:**

Met Mr. Ken Peterson at administrative office prior to entering AltEn property. Mr. Peterson advised ice falling from digester roofs; keep clear of falling ice. Observed Clean Harbors Mobile Command Center parked in AltEn admin. office parking lot. No activity observed in or near

command center. No vehicles with Clean Harbors marking observed on property. No cleanup activity observed with the exception of pump connecting south digester to lagoon to the east and ice structure on north digester being melted with steam. I met Terracon representative James Koehler at Stops #1 and #2.

